Notebook, N-90-01-04.5

This notebook covers the period January 1890-April 1893. All entries are by Edison. The book contains notes, drawings, and calculations relating to ore milling, including what appears to be a list for a patent caveat. There are also electric railway drawings and notes for a series of chemical experiments. The front cover is labeled "#583"; the number has been crossed out. The inside front cover is inscribed "#583 T A Edison Jan 4. 90." The book contains 182 numbered pages and has been used in both directions. Two pages were removed before the book was paginated.

Filming order: 1-147, 182-152.

Blank pages not filmed: 2-3, 48-139, 148-151.

N-90-01-04.5

#583

M Edlow
Jan 4. 90

XE-5286







	Sp grav	Hardness	Streak	Fracture	Phenom	Color
Pyrite – FeS_2	4.83 @ 5.2	6 @ 6.5	greenish or Brownish Black	Conchoidal uneven Brittle –	Struck fire with steel	Pale brass yellow
53.3 Fe 46.7						
Nr Co Cu Thallium sometimes replaces a little of iron –						
Closed tube S sublimes Reacts Magnetic						
Ins HCl Dec Nitric –						
Cubanite			Dark Reddish Brown to black.			Brownish chrome yellow
5.39 Cu 20 Fe 38						
Sq – 4.02	H 4					
Closed tube sublimate.						
Chalcopyrite	4 @ 4.3	3.5 @ 4	greenish black	Conchoidal uneven	Subject to tarnish from moisture	Brass yellow
35 S. 34 Cu 30 Fe	Thallium + Selenium present	Sometimes			Can distinguish with a knife	
Closed tube decrepitates – Sub of S						
Ins in Nitric Except S green Solution						
Nit in Excess changes to dirty blue						

Stannite

H. 4 – G 4.3 @ 4.5 Lustre metallic
Streak blackish. Color steel gray to
iron black – the former when pure, sometimes
bluish – often tarnished from Chalcopyrite.
Opaque – Fracture uneven Brittle,
S 30 Sn 26 Cu 30 Fe 12 @ 6.
Zn 7 @ 8. Close Stroke decrepitates
faint sublimate. open tube of Sn Oxide,
Dec Nitric blue sol separates Sn oxide Tin

Linnaeite –
H 5.5 G 4.8 @ 5 Lustre metallic

1600 mesh

5
4

20 tons
5
50 tons hour

1000 lbs
200
2000

10 +

27
4

100.

10800 –

1 pair rolls 50 ton-hours } net 10 ton 1000 m
50 screens = } in 20 hours

10 pair rolls — 500 screens.

25 000 -
10 000 -
5 000 -
12 000 -
3 000
10 000
65 000 -

1500 -





Pyrite, Gran 4.83 @ 5.2 –

S 53.31 Fe 46.17 67 weight-

Calcopy – G 4.1 @ 4.3

Cu 34. S 35.18 Fe 30. 82

42

Muspickel. G 6. 6.4

As 42.88 S 21. Fe 36. 50

Pyrrolite. G 4.4 @ 4.68.

S .38. Fe 57. Ni 3

S 40.15 } 84.

Fe 54.18

670

66

44 2 0

71 40 2 0

44 2 0

30 / 70 (233

60

100

95

100 47 24 67. 428 lbs to 10 lbs.

470

66

28 2 0

282 0 (19.9

16 / 31 9

16

154

144

6 oz

470

7 / 30 (4.28

28

20

14

60

6 g to 1 lb

1/2 oz to lb

16 oz

12

6) 16.0 16) 70 (26

6

420

32

100

64

700

65

350

42 00 0 (28

45

32

13

128

10 m. l.

783

Mining 25-
Crushing To 40 mesh - 25-
Concentrating 10
60-

Must have 1/1 to pay.
Crude ton 220 lbs pyrit.
or 1/6 per ton Conc



Conc -
Drying 3
Sensorosity 10
Magnetite - 10
Dead Roasting - 75
Re Crushing 9 — 50
148
Bridging Iron — 123 — 35-
Making Copper 148
308

Total 908 -
Get 75% of ore - at 1/3.
908
225
683
Total
Quality
Total
1000
683
317

60000

908.
600
3.08.

18000.
18000
36,000 -

2-

5000 -
24
20000
10000
12000
250
25
9
225 -
62
300
8000

33
22
66
2240) 275000 (123
2240
3500
3360
140
66
74
185 -

3 | 225 -
1 | 75 -
3
375 -

375 - Cu
225 - Fe
600 -
2

60
300
18000.

10.

30

175
30
5250




17


19

36–

49
7
392
343
3822

36
7
288
252
2808





Note – Vol. I to V.
on pgs 25–47 refers to
Watts, Dictionary of Chemistry
1883 Edition
N.R.S.
10/6/03

Miscellaneous –

By action of ammonia on aconitine a number of products are obtained of indefinite character –

Accord Aconitic acid – aconitate Calcium gelatinous when nearly dry then Resin. –

Albumen Combines with Lime, product dries after while hard as stone also combines with Na K Bycits &c

Chloride Cal combines with Alcohol to white amorph mass see Vol I – 80 –

Sulphide of Allyl form with a gum Trichl of gold beautyl yellow pp – Calcetta Rasinous mass & becomes covered with fulmo gold. Vol I 144 –

Sulphide Platinum – pp – when Dried at 100 C takes fire & glows until reduced to Pt – Lamp –

~~Others~~

Antimonides of Methyl —
Hydrati = Storage batt Vol I 395 —

Arsenic alloys wi Cu white Malleable
ppty no forecastle,

Arsenite of Sb. Transparent fused
Vitreous mass

do-arsenate Aluminum

Stannous Arsenate, gelatinous

Sulpharsenite Tin — gummy

Sulpharsenate Silver grey Pulvite/Cake

Hydrolysis Metallic lustre,

Cyanide of Cacodyl — for War —

Bromide Gold reduced Pt dec by slight
heat = (Heat photography) —

Chrysammate KO Crystals peculiar effect of light.

Cinchonidine Electric by friction.

Sulphate Cinchonine Becomes phosphorescent at 100 C.

Sulphate of Iodocinchonine Crystals act like tourmaline to light

~~Cocoa~~ Coca wax strongly Electrical by friction

End Vol I

Cobalticyanide + Hydrogen
heated to 250C leaves blue
powder at higher temp Carbide
of Cobalt, black is it a Cyanide

Carbide gold 214 2nd —
" grun — 222.

Platinocyanide Strontium — white
but so sensitive to moisture that
breath turns Crystals blue —

Sulphydrate Calcium takes hair off
Formate Hg decomposes in dark
also by passage in Crystals or 100C heat

Formate Silver ewentuous
black in the dark See Kennedy

Fulminate Silver
gradually blackens when
exposed to white or blue Light

Chem compound of Gelatine
& phos Calcium is Allantoin

Glucinium dont combine
with Sulphur at any
temp - forms alloy
with Silicon -

glycerides on Chloroform
& Alcohol -

Guiacum Violet rays Spec
tum green - Red ray

restores the yellow color

End 2nd Val

Protochloride of Iodine - Chlorine
removes an H & Iodine goes in -
to Iodine places -

Barium salt of Isothionic acid
swells up over 100 times its
bulk — KO salt melts
350 & Sales defines to a material
like porcelain — without
loss weight

Copper amalgam expands on setting
& highly plastic like clay

Iron amalgam - magnet (10) Hg
globules magnetic - Ampere's -

Mercuric oxide the weakest of all
basic oxides being only salt
ppt from its salts by water alone

Boric Methide, takes fire
& part in air bright green flame
~~steam~~ if steam through tube
in air amount of smoke
surprisingly great. 2 or 3 Centro
inches of gas burnt this way
fills large room full Carbon
flocks flame mixes & hours
Can be used in it Vol 3 906

Methylamine is the most soluble in water of all known gases

Molybdenum harder than Topaz —

phosphide of Molybdenum

Conducts Electricity diffusion

Volatile Oxs when cold dissolve Oxide Copper & deposit the Ox on heating = Ox

Oxivid - Room electric

Oxalate Calcium dry highly Electric

Palassco-Manganese Oxalate
precipitate very easily
decomp Light & heat

do Ammonio-mercuric Oxalate
do Palassco-mercuric "

See - 432 - IV Resorcin Ether

Hydrochlorate of Chloraniline
the Chloroplatinate of a-chloraniline
gives violet color on exp. to light

Ethylaniline turns Green
on exp to Light or air -
amylaniline odor of
Rosco

See - ~~Phosphorus~~ Boron Hydrolic

Ethylate - 479 — IV

+acetate " "

Phosphite Chromium dry salt

on heating gives off pure

Hydrogen

Hydrosulphide of phos. dissolves in C-S,

Shines in dark — 599 — IV

Piperine - See 659 IV Electric

Tripotassamide - for red +some blue

Else for white boiling in air

in Vac by Crack — Vol IV 695

Pot + Phos under Naptha

must only boiling Naptha

See B-8510

Watts Dictionary of

Chemistry

Tartrate or Citrate boil ignited
~~with~~ make a
pyrophoric stuff - might seal
in Vac + then slowly permit
O in =
Sulphides KO Na Lithium
Obtained by igniting
Corresponding sulphates with
Lampblack —
Alum or Homburgs pyrophorous
by heating alum with
Lampblack, starch, or flour
Exhibit sparkamm inflam.
IV 765-6 —

Hydroferrocyanate Quinine
Resemble Mosaic gold
20 Val V
Iodoquinine effect of light fumy
Val V 25

Pyrotartramide (with oxide Lead) dissolves proper
+ Cant be fitted

gun Cotton when ignited in small
quantities in rarified atmos
Exhibits 3 dif Luminous phenomena
in my Vac beautiful green glow
in vac yellow yellow etc
good = See pyroxylin IV 780

3rd Sup pt 2nd Oils volatile
See Oxidation p 1430 —

April 10/93

1 The use of 3 or an odd number of rolls —

applying pressure to the Crushing

2 Rolls by a multiplying rope with 2 or more reels

3rd arranging one rail above the other.

4th first passing the ore through one Roll then the other.

5 Important in such of crushing Crushing in producing great pressure between the Revolving Crushing rolls by the multiplying action of moving ropes or equivalent devices arranged such as described so that such pressure without Transmitting such pressure through fixed bearing surfaces —

The use of a spring or equivalent weight producing a constant but relatively small tension on a traveling rope a multiplying such tension many times to produce great pressure between rotating Crushing rolls such as set forth,

The fixed sheave ~~[illegible]~~ movable sheave take up,

Two rolls alone could be used the rope on the sheave crossing at each turn, but the Method of application is not so effective as with the 3 rolls —



144



50 | 6000 | 120
300
100
= 120 cars

14 cars

10

1200 | 6000 | 5 min.
20
40 =







[THIS BOOK WAS USED IN BOTH DIRECTIONS. THE FOLLOWING PAGES WERE FILMED FROM THE BACK END FORWARD.]



8, mills, 800 acres
opening lines: 80 acres
RR - etc. 200 acres
1,080 acres,

8 Mills.
8000 tons daily

285
8
2280, tons daily.
570

18,000, 6360

40
8
320,000.

2280, 6360.
12 3180
2280 Crushg etc. Roya. 948
570
2280
3180
313



081


40
350
2800.
60
75
3000
23,500
500 | 1090 - 1
450
400
5
2.00
2.25
4.25
333 | 1040 - 13
390
450.
404 | 1040 | 2.50
1010
1000
400.



1000 60c

3c per 100 lbs - Mining & Milg -

15 pc on 12 net. ~~800~~

Expenses $600.

10 pc on 125 tons. at 500 - 550 & 1020 180 -
5.00 825 - profit 225 X
15 " 150 " 500 1000. " 400 X.
20 " 250
25 " 250

10 pc on 125 - 500 50c 625 - profit 25 -
15 - 187 - 339 -
20 - 250 - 650
25 - 312 960
30 374 1270
35 - 436 1580.
40 498 1890

125 / 5.00 (25 1000 (8. 3 / 1000
125 1000 (2.5
250.

Statement on Survey for

10 pctone 2.5-C Raw Ton

9600

1.27 | 16.00 6

1000 | 335-0 (33.5
300 00
35 00
2 500
500


1 - Hot Melt
1 for Hot Melt Coat


EKR
Dec 10 '90


EKR
Dec 10 '90
OLI

EPR
Dec 10-90



EPR
Dec 10/90








EKK Dec 09
EKK Dec 09




Erik Dec-10/90
N
S
S
N
N
S
S
N
N
S
S
N



28000 ft in hour

12-

$$
\begin{array}{r}
28000 \\
33000\overline{)\,5\,60\,00\,00} \\
33\,0000 \\
23\,0000 \\
19\,8000 \\
\hline
3\,20000 \\
2\,97000 \\
\hline
23000
\end{array}
\qquad 1696.
$$

$$
60\overline{)\,1696.}\ 28
$$




800-
650-
32-
15-
493
4½
43
3.50
1.50
329
3300
25000
650
2500
1500
1250
1000
1.50
300
250
50
4.50
3
1.50


O/C


O/C for distilling



1. 20 gms

1/1000 - 20

100 / 5.0 / 20 / 0.

4 x 4 2 grms or 5 grms gel



2.50
2.50
12.5
5.00
62.5 4/1000 - 5000

120/5000/41.
480
200
120

41
4 / 164 mg
8
820.

75°

154